

# SERVICE BULLETIN



No. : 0IVL20060050

Date : 2006-03-02

Model	Factory	Factory Model	Suffix	Model No.	Factory	Factory Model	Suffix	Model No.
	EKHQ	42LP1D-AA	ALAULL	42LP1D				
Buyer	Buyer Name	Buyer Code	Buyer Name	Buyer Code	Buyer Name	Buyer Code		
	LGEUS	US000001	LGEAI	US000002				
EFFECTIVE DATE	2006-03-02		EFFECTIVE FROM(SERIAL NO.)			.		
Subject	LCD Digital TV Software for Australia - Lip Sync Problem							
No.	Loc No.	Before Change		After Change		Note	K-Code	Remark
		Part No	DESC./SPEC.	Part No	DESC./SPEC.			
<b>Reason Of Change</b>								
<p>Symptom : lip Sync problems with the above models on the HD stations</p> <p>Cause : Because of software revision for jitter_bound setting</p>								
<a href="#">Lip sync_SVCbulletin.pdf</a> <a href="#">SW Download Program, Manual.zip</a> <a href="#">SoftWare File_LCD.zip</a>								

\*\* FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

NOTE(**) : INTERCHANGEABILITY CODE				KEY-WORD CODE
	Parts	Set		
A	Original	Early		1. To improve performance 2. To improve productivity
	New	Late		
B	Original	Early		3. To improve reliability 4. Change of material or dimension
	New	Late		
C	Original	Early		5. Addition 6. Deletion
	New	Late		
D	Original	Early		7. Correction
	New	Late		

CHIEF ENGINEER , *approved*  
 Factory.